PREPARED FOR SUBMISSION TO JINST

20th Anniversary "Trento" Workshop on Advanced Silicon Radiation Detectors 4–6 February 2025 FBK, Trento, Italy

Pixel column issue in the ATLAS Inner Tracker modules

L. Meng, ^{*a*,1} R. Bates, ^{*b*} C. Buttar, ^{*b*} G. Calderini, ^{*c*} F. Crescioli, ^{*c*} L. Cunningham, ^{*b*} Y. Dieter, ^{*d*} R. Han, ^{*b*} T. Heim, ^{*e*} S. Hirose, ^{*f*} F. Huegging, ^{*d*} C. Hultquist, ^{*e*} D. Kim, ^{*g*} A. Korn, ^{*h*} M. Marjanovic, ^{*i*} J. Metcalfe, ^{*g*} K. Nakamura, ^{*h*} J. Pater, ^{*k*} H. Pernegger, ^{*l*} M.A.A. Samy, ^{*b*} M. Schuessler, ^{*d*} A. Sharma, ^{*k*} E. Thompson, ^{*e*} M. Backhaus, ^{*m*} J. Christiansen, ^{*l*} F. Loddo^{*n*}

^aLancaster University, LA1 4YW Lancaster, United Kingdom

^bUniversity of Glasgow, United Kingdom

^cLPNHE, Paris, France

^dUniversity of Bonn, Germany

^eLawrence Berkeley Laboratory, Berkeley, United States

^f University of Tsukuba, Japan

^gArgonne National Laboratory, United States

^hKEK, Japan

ⁱUCL, London, United Kingdom

^jUniversity of Oklahoma, United States

^kUniversity of Manchester, United Kingdom

¹CERN, Switzerland

^mETH Zuerich, Switzerland

ⁿINFN Sezione di Bari, Italy

E-mail: lingxin.meng@cern.ch

ABSTRACT: Pixel modules are currently being built for the ATLAS ITk Pixel detector upgrade. During the preproduction phase, recurring chip malfunctioning was observed during electrical testing. It was possible to bypass this issue by disabling some pixel core columns in the ITkPix readout chip. Therefore the issue is called "core column issue" which is a direct disqualifier for a pixel module. A concerning number of cases has been observed in pixel modules with ITkPix v1.1 as well as v2 chips which significantly impacts the module yield. However, the behaviour is erratic and there is not any evidence hinting at the origin of this issue. These proceedings outline the investigations of the issue, highlighting the electrical behaviour during testing, present findings from the data collected via our production database and through visual inspection, and point towards possible causes of the issue.

KEYWORDS: Detector design and construction, Front-end electronics for detector readout, Hybrid detectors, Particle tracking detectors, Solid state detectors

¹Corresponding author.

Copyright 2025 CERN for the benefit of the ATLAS Collaboration. Reproduction of this article or parts of it is allowed as specified in the CC-BY-4.0 license.

Contents

I	Introduction	1
2	Core Column Issue	2
	2.1 Statistics	2
3	Investigations	3
	3.1 Probing of diced chips	3
	3.2 Inconsistencies and analog dependencies	4
	3.3 Mechanical damage	4
4	Conclusion	7

1 Introduction

The Inner Tracker (ITk) is the upgrade tracker for ATLAS [1] in the High Luminosity (HL)-Large Hadron Collider (LHC) era. The pixel detector [2] is currently in its production phase, with more than 10000 hybrid modules being built. The modules come in two flavours: quad modules (figure 1a) consisting of four front-end (FE) chips and a quad-size planar sensor tile of about $4 \times 4 \text{ cm}^2$, and triplet modules of different geometries, figure 1b, consisting of three bare modules, each made of one FE chip and one single 3D sensor tile. In the ITk pixel detector, about 95% of the modules are quad modules while 5% are triplet modules.

The FE chip was developed by the RD53 collaboration [3] for both the ATLAS and CMS inner tracker upgrade for the HL-LHC. They differ only in the size of the matrix and in the analog pixel circuit. The ATLAS variant is called "ITkPix" and consists of 400 columns \times 384 rows, resulting in a total of 153600 pixels. The digital logic is grouped into 50 core columns (CCs) as indicated in figure 2a, where each core column consists of 8 pixel columns.



Figure 1: Two pixel module flavours: (a) a quad module, (b) a linear triplet module.



Figure 2: (a) The ITkPix chip layout: pixel matrix (left) with core column logic (right). (b) Occupancy map from a digital scan with 100 injections on a module with some core columns disabled (marked in green). The bottom right chip was not wirebonded.

2 Core Column Issue

Throughout module preproduction with ITkPix v1.1 and during production using ITkPix v2, certain chip malfunctioning is observed on chips classified as fully functionining - "green" - by wafer probing. The symptoms are erratic and not consistent, e.g. chip readout is stuck, or chip sends continuous bad data etc. Chip operation can be recovered by disabling one or more core columns (figure 2b) so that the chip behaves normally. Thus this kind of chip malfunctioning is called "core column issue". Because a core column contains 2% of the pixels on the chip, disabling one core column would directly fail a module by our current quality control (QC) criteria (total <1% bad pixels). This issue is observed on ITkPix v1.1 modules and ITkPix v2 modules, as well as by CMS on their CMS Readout Chip (CROC) v1 modules.

2.1 Statistics

To obtain an overview of the frequency with which the core column issue occurs, queries were made to the ITk production database (PDB) [4] which records information of all components, their stages and tests. FE chip configurations were queried to obtain the settings of the core-column-enable registers which contain information about disabled core columns. A snapshot of the CC statistics is shown in table 1. The data are sorted by chip version and testing temperature in order to show any systematics.

The largest amount of the data are from warm tests on v1.1 chips assembled in both quad and triplet modules, therefore they are used in the following investigations. Figure 3 shows fractions of chips (3a) or modules (3b) with CC issues, which are similar across all hybridisation vendors, showing that the issues are not associated with one vendor. The number of FE chips that are disabled in software during testing is also indicated in figure 3a. This could be due to either the user not associating errors with the core column issue, or other issues such as the chip is not wirebonded due to damage of the wirebond pads or wirebonding failure. Therefore, disabled chips are not included in the number of FE chips with CC.

Figure 3c shows the distribution of all disabled CCs for all hybridisation vendors. The distribution is uniform across FE chip except for the edges where an increase is seen. The increase in

Table 1: Data extracted from the production database. The columns "CC/chips(modules)" are fractions of chip (modules) with at least one disabled CCs out of the total number of chips (modules). The testing temperatures "warm" and "cold" correspond to about 20 °C and -15 °C, respectively.

chip version	testing temperature	CC/modules	CC/modules (%)	CC/chips	CC/chips (%)
v1 1	warm	77/357	21.6	116/1393	8.3
V1.1	cold	42/249	16.9	57/982	5.8
w2	warm	17/118	14.4	25/470	5.3
v2	cold	9/85	10.6	12/340	3.5



Figure 3: Fraction of chips (a) and modules (b) with disabled core columns per hybridisation vendor. (c) positions of disabled CCs on all problematic chips.

disabled edge columns is associated with one vendor. The position of chips on wafers were studied as shown in figure 4. While the cumulative map (figure 4a) does not show any preferencial position for CC chips, looking at individual wafer maps reveals that CC chips often cluster together in a row or in a column which could indicate problems with dicing or picking, like shown in figure 4b.

Other variables, such as the assembly or testing date or site, sensor leakage current etc, showed no relation to the core column issue.

3 Investigations

Intrisic issues of the design or the chip itself can be excluded to be origins of the core column issue because such would have been identified, flagged or rejected accordingly during the probing of the FE chip wafers. The only stages at which changes happen to the chips are between wafer probing and initial testing, which would be hybridisation and module assembly. In the hybridisation stage, chips are bump-deposited, thinned, diced and flip-chipped into a bare module. The bare module is glued onto a flexible module printed circuit board (PCB) and wirebonded in the assembly stage. Especially hybridisation is a delicate process during which mechanical damages can occur.

3.1 Probing of diced chips

To test this hypothesis, 63 and 25 diced ITkPix v2 chips from two different wafers were probed. While the former were all probed to be "green" on the wafer level, the latter were not probed prior to dicing. Only four from the originally green chips had any pixel issues, which are still categorised



Figure 4: (a) Cumulative wafer map with occurence of CC chip position. (b) example wafer map where CC chips often appear in consecutive oder in a row or column. The z-scale indicate the location of disabled core columns on that chip.

as "green" after probing. Two of them had bad double-column bias to the analog FE circuit, and the other two chips likely had data acquisition (DAQ) instability that showed up in the scan mask pattern. None of them showed CC issues based on what has been observed.

3.2 Inconsistencies and analog dependencies

Bad core columns often manifest themselves already at register reading or in digital scans, but also analog dependencies have been observed.

Very few CC cases can be potentially narrowed down to bad pixel regions $(4 \times 1 \text{ pixels})$ as shown in figure 5a or bad pixel cores $(8 \times 8 \text{ pixels})$ as shown in figure 5b. Once these smaller areas are disabled, the chip can function normally without disabling the CCs. This would drastically reduce the number of bad pixels overall on a chip compared to disabling entire core columns.

CC issue often shows inconsistent symptoms even within the same chip. One example is figure 5b, where the bad pixel core was hard to find. While the software diagnostics tool cannot find any bad CCs in this chip, the analog scan often fails, indicating CC issues. Only when sometimes an analog scan runs successfully, this bad pixel core can be seen in the occupancy map.

CC symptoms sometimes show dependencies on the analog settings, for example threshold or injection charge. Figure 5c shows a bad occupancy map of the chip with CC issue when the injected charge is 1650 e. The same chip behaves normally when the injected charge is 2600 e as shown in figure 5d.

When a chip gets stuck due to bad CCs, a reset signal must be issued, which is not the normal mode of operation. Modules with continuous data output were studied to confirm that these data cannot be decoded.

3.3 Mechanical damage

Core column issues were observed on badly diced chips. Therefore, we tried to obtain a correlation with mechanical damage.



Figure 5: (a) Map from a pixel test highlighting a bad 4×1 pixel region. (b) Occupancy map from an analog scan with a bad 8×8 pixel core with mostly 0 hits. (c) Occupancy map of a module at 1650 e injection charge. (d) Occupancy map of the same module at 2600 e injection charge.

First hint The first confirmation of mechanical damage causing the CC issue was an accident in which two previously functional modules developed CC issues. On one module the CC issue was reproduced in a different chip by rotating the module by 180° in the same setup. Only under certain angle and with the correct lighting conditions, some cross or pyramid pattern was found on the back side of the FE chips, which could be a crack in the silicon as can be seen in figure 6. The location of this crack lies in the area of the disabled CCs on the chip. Investigations found the cause to be a bump from a solder splash of about 100 μ m size on the vacuum chuck used in that particular setup.

Visual inspection Visual inspection of many affected modules were done. While a few known chips with bad dicing edges, as shown in figure 7a, had core column issues, most CC modules collected for this campaign did not show any visible bad dicing as shown in figure 7b, or any damage on accessible part of the chip, e.g. the backside or around the wirebond pads. There was no clear correlation between modules with CC issue due to bad dicing. Bad CC issues can be associated with poor dicing, but poor dicing does not necessarily imply CC issue.

Induce surface damage From the diced single ITkPix v2 chips in section 3.1, mechanical damage was induced trying to provoke core column issue. Each chip is divided into several sections as shown in figure 8a. In each of the sections, a different scratch pattern with varying strength was induced via probe needles. An example of a scratch is shown in figure 8b. The chips were then



Figure 6: A quad module has developed core column issue. Careful visual inspection revealed a crack within the area of disabled core columns which came from a solder splash on the vacuum chuck.



Figure 7: Different quality of dicing edges in v1.1 and v2 chips. Core column issues have been observed both on chips with bad (a) and good (b) dicing edges.



Figure 8: Destructive test on diced v2 chips by inducing different scratch patterns in different regions of a chip (a) and (b). The result was a chip with partially damaged double-column analog bias that is visible in an analog scan (c).

probed again to test for any induced damage. From the two scratched chips, one ended up dead, the other one suffered a damaged double-column analog bias from one of the scratches, as can be seen in an analog scan in figure 8c. This agrees with expectations as the power distribution of the chip happens in the top metal layers. However, core column issues were not induced by this scratching test.

Rejected chips Chip defects were studied that were grounds for rejection by hybridisation vendors. Six vendor-rejected chips with different defects were collected, visually inspected with a higher



Figure 9: Top: damages of two vendor-rejected chips which exhibit core column issue. Bottom: defects of four vendor-rejected chips without core column issue.

magnification and tested on a probe station. Using the same software to test all these chips, the two chips with what looks like chipped edges as shown in the top row in figure 9 had CC issues while no core column issues were found on the other four chips with bump defects as shown in the bottom row in figure 9.

Destructive tests Two modules with CC issues from the same vendor were disassembled by heating up on a hotplate, shown in figure 10a, and using vacuum tools to pull apart the chips at the melted solder bumps. Three defects were found on one of the chips, shown as an example in figure 10b, where defect 1 and 3 are similar as can be seen in figure 11. The location of disabled CCs agrees with the location of defect 3. The appearence of the defect correlated with the CC issue on the second module is the same as defect 3. An energy-dispersive x-ray (EDX) measurement revealed that the extra material consists mostly of silicon, which may be due to some debris from dicing that got between the FE chip and the sensor during hybridisation.

4 Conclusion

The core column issue observed on pixel modules affects about 20–25% of ITkPix v1.1 and v2 modules. Our investigations uncovered inconsistent symptoms in the behaviour of the chip, showed potential dependency with chip's analog settings and confirmed the cause being mechanical damage as we first suspected. While we are investigating deployment of enhanced QC procedures at hybridisation vendors, we also prepare to check for bad core columns within our module QC procedure by using the software tools developed. However, due to the origin of the issue, the development throughout the whole QC process and longterm impact are not yet known, especially regarding handling, thermal stress and irradiation. Impact on tracking performance is being studied via simulations.



Figure 10: (a) A module on a hotplate (left). After successful disassembly, four chips can be seen on the hotplate (right). (b) Defects found on one disassembled chip. Out of the three defects, the location of defect 3 agrees with the location of the disabled CCs in a scan (c).



Figure 11: Top: defect 1 does not correspond to a disabled CC. Bottom: defect 3 is associated with a disabled CC (same appearance as on the second disassembled CC module). (a) birds-eye view of the defect. (b) 3D view of the defect. (c) measured dimensions of the defect.

References

- ATLAS Collaboration, *The ATLAS Experiment at the CERN Large Hadron Collider*, JINST 3 (2008) S08003
- [2] C. Buttar for the ATLAS ITk Collaboration, ATLAS ITk pixel detector overview, doi: 10.1016/j.nima.2024.169978
- [3] RD53 Collaboration, *RD53 pixel readout integrated circuits for ATLAS and CMS HL-LHC upgrades*, JINST 20 (2025) P03024
- [4] M. Wielers for the ATLAS Collaboration, *ATLAS ITk Production Database use and tools*, ATL-ITK-PROC-2025-006, CERN, Geneva (2024).